

Attachment to replacement bulletin february 14 2003

## Color check

The valve cone assembly in question has a silicone sealing that is transparent. If the silicone sealing is red, blue or white it does not need to be replaced.

